



**Studebaker**

AUTOMOTIVE SALES CORPORATION

SOUTH BEND 27, INDIANA

**Service Letter**

**PARTS AND SERVICE**

**SUBJECT** IMPROVED SUN VISOR ROD  
RETAINING BRACKET

**FROM** C. R. MCINTOSH, Manager  
Passenger Car Technical Service

**NUMBER** F-1964-3

**DATE** October 31, 1963

Effective with production of approximately October 17, 1963 a new and improved sun visor rod retaining bracket is used on 1964 model passenger cars. The improvements to the bracket include a thicker and a flat base as well as a radius added to the internal portion of the bracket. These changes will strengthen the bracket and reduce breakage.

The new bracket, part number 1359591x1, can be installed on prior models. However, when installation is made on a 1962 or 1963 model, or on 1964 model Convertibles and Station Wagons with stationary roof, a No. 8 external tooth lock washer is to be installed between the bracket and the windshield opening header.

The new bracket is available upon order from your Parts Depot.

CRM/et